

Oil Field Environmental Incident Summary

Incident: 20170602165631

Date/Time of Notice: 06/02/2017 16:56

Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Name: YOGI 14-7H-0607-15895-TF

Field Name: TEMPLE

Well File #: 26825

Date Incident: 6/1/2017

Time Incident: 21:30

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 95

Sec: 7

Qtr:

Location Description: On well site and farmed land immediately adjacent to wellsite.

Submitted By: Michael Ellis

Received By:

Contact Person: Michael Ellis

1200 17TH STREET, SUITE 2200

DENVER, CO 80202

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

2 Mile

Distance Nearest Water Well:

2 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units
Oil	10	Barrels

Recovered	Units
-----------	-------

Followup	Units
----------	-------

Brine

Other

Description of Other Released Contaminant:

5 bbls of oil released offsite in to adjacent pasture. 5 bbls of oil released and remained onsite

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Fire hazard from oil. H2S.

Areal Extent:

5 bbls off site over an area of 5 acres

Potential Environmental Impacts:

Impact to surface only. Contaminated soils.

Action Taken or Planned:

Removing contaminates soils from the location for disposal.

Wastes Disposal Location: IHD Environmental Williston (Indian Hills)

Agencies Involved:

Updates

Date: 6/7/2017 **Status:** Reviewed - Follow-up Required

Author: Torgerson, Brad

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited site on 6/7/2017 at 5:50 PM - Sunny and 78 Degrees F - What appeared to be crude oil stained crops were observed for several hundred feet NW of the location. The production location appeared to have been recently cleaned-up. See images

Date: 7/6/2017 **Status:** Inspection

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 12:30 on 6-29-2017. The weather was hot and sunny. Release went northwest off the well pad. It spans several hundred feet. The vegetation appears oily and there is staining on the ground. A soil sample was taken at N48.561813 W102.929657. The party representative said that an agreement was reached between the land owner and the company where they would compensate him in the fall for the amount of product lost. The land owner wants no remediation done. Further follow-up is needed.